

A32

1

2



ESR

3

DC-Link

1200 $\mu$ F



	$\pm 5\%$ $\pm 10\%$
	$2 \times 10^{-4}$
	$20 \times 10^{-4}$ 1V 100Hz
	1.5Un 10/60s
	2Un+1000 Vac 60s
	-40 ~+70
	-40 ~+85
	100000
	40/85/56

-----